



IP Office Technical Bulletin

Bulletin No: 152
Release Date: 22 March 2013
Region: Global

General Availability (GA) of the IP Office Release 8.0 Q1 2013 Maintenance Release

Avaya is pleased to announce the availability of the IP Office Release 8.0 Q1 2013 Maintenance Release. This is a scheduled Maintenance Release addressing a number of field issues found in the IP Office Release 8.0 GA software.

1 Overview

This Maintenance Release incorporates new software for:

- IP Office Core Switch 8.0(56)
- IP Office Preferred Edition 8.0(4002) (also known as VoiceMail Pro)
- Customer Call Reporter 8.0.12.8
- one-X Portal 8.0.106(10)
- IP Office Application Server 8.0.30(2)
- Unified Communications Module 8.0.10(2)
- User CD 4.2(48)

The IP Office Administration and application software can be downloaded from the Avaya Support Website:

<http://support.avaya.com>

This software is for use with the IP Office IP500 and IP500v2 systems.

IP Office Administration consists of the following software:

Delivered Software or Package	Version
IP Office Firmware	8.0.56
IP Office Manager	10.0.56
System Monitor	10.0.56
Upgrade Wizard	10.0.56
Network Viewer	10.0.56
SSA Viewer	8.0.56
4610SW, 4620SW, 4621SW, 5610SW, 5620SW, 5621SW	2.9.1
Telephone Firmware	
4601, 4602 Telephone Firmware	2.3

Delivered Software or Package	Version
4601+, 4602+, 5601+ and 5602+ Telephone Firmware	2.9.1
4625 Telephone Firmware	2.9.1
5601, 5602 Telephone Firmware	2.3
2410 / 2420 Telephone Firmware	R6.0
5410 / 5420 Telephone Firmware	R6.0
1403 Telephone Firmware	6.0
1408 / 1416 Telephone Firmware	R32
1408 / 1416 Loader (Boot File) Firmware	25
9504 / 9508 Telephone Firmware	R45
9504 / 9508 Loader (Boot File) Firmware	R15
IP Office Video Softphone (Windows)	3.2.3.48.67009
IP Office Video Softphone (Mac)	3204bk.66292
IP DECT – ADMM Firmware	1.1.13
IP DECT – ADMM Java Configuration	1.1.13
IP DECT – ADMM DECT Monitor	1.4
3701 Telephone Firmware	22.04.04
3711 Telephone Firmware	91.24.31.04
3711 Global Telephone Firmware	91.24.36
3711 Global Telephone USB driver	0.8
T3 IP Telephone Firmware	T247
T3 IP Admin Tool	3.08
1603, 1608, 1616 Telephone Firmware	1.3200
1603 Loader (Boot File) Firmware	1.3200
1616 Button Module Firmware	1.1.0
9620 / 9630 / 9640 / 9650 Boot Code	3.2.0
9620 / 9630 / 9640 / 9650 Telephone Firmware	3.2.0
9621 / 9641 Telephone Firmware (Application file)	6.2.2.09U_V452
9608 / 9611 Telephone Firmware (Application file)	6.2.2.09U_V452
9608 / 9611 / 9621 / 9641 Kernel	V13r50
1120E 1140E 1220 1230 Telephone Firmware	04.03.12.00
3720 Telephone Firmware	3.3.16
3725 Telephone Firmware	3.3.16
3740 Telephone Firmware	3.2.15
3749 Telephone Firmware	3.2.15
DECT R4 – IPBS 1 and IPBS 2 Firmware	5.0.11
DECT R4 - IPBL (DECT Gateway) Firmware	5.0.11
DECT R4 - GRBS (ISDN RFP) Firmware	R5C 3/40
DECT R4 – AIWS Firmware	2.73
DECT R4 – AIWS2 Firmware	3.13
DECT R4 – WinPDM	3.8.2
DECT R4 – Rack Charger Firmware	1.4.1
DECT R4 – Advanced Charger Firmware	1.4.1
3641 / 3645 Telephone Firmware	117.056
Avaya Voice Priority Processor (AVPP) Firmware	17x.039
Handset Administration Tool (HAT)	2.8.22.0

Note: Upgrading IP DECT 3711 Telephone Firmware to 91.24.31.04

This Administration CD contains two upgrade programs with this release of 3711 telephone firmware:

pp_avaya_3711_91_24_31_04.exe
up_avaya_3711_91_24_31_04.exe

Please check the handset label located under the battery cover to determine the month and year of release. If the handset has a date of 08/06 or earlier then use the “pp” upgrade program. If the date is newer than 08/06 then use the “up” upgrade program to update the telephone.

This release supports the "IP DECT 3711 Global" telephone. The Global telephone will not offer any different feature set than the current 3711 but will support both EMEA and US frequencies. To determine if a customer has a “Global” 3711 telephone press Menu, System, Version Number. The PRD: number will end with a suffix of “.int”.

2 New Features

2.1 Microsoft Windows 8 Support

This release includes support for the Microsoft Windows 8 Operating Systems including “Pro” and “Enterprise” (32Bit and 64Bit architectures). Currently, this does not include the following applications:

- IP Office Video Softphone
- Contact Store
- one-X Portal Plug-in for Salesforce

A separate announcement will be made when support is available.

2.2 Microsoft Windows Server 2012 Support

This release includes support for Microsoft Windows Server 2012. Currently, this does not include Customer Call Reporter (CCR). A separate announcement will be made when support is available.

3 IP Office Resolved Field Issues

In the table below, the JIRA number refers to the internal bug tracking database used by Avaya SME. When a customer field issue has been confirmed to be a product or documentation issue, it is logged in this system, and the JIRA number used internally within Avaya for tracking the resolution of this issue. There may be several customer field cases raised against a single JIRA entry.

3.1 Resolved field issues in IP Office 8.0(56) and Manager 10.0(56)

The following field issues have been addressed in 8.0(56) and Manager 10.0(56):

<u>JIRA Number</u>	<u>Description of Issue</u>
IPOFFICE-32929	No subsequent retry for SIP Registration on receiving "400 Bad Request" response
IPOFFICE-32161	FNE32 call from SIP trunk - call will not connect when call is targeted directly to DECT extension
IPOFFICE-35936	Memory related system restart on 8.0.448411
IPOFFICE-33018	Outside calls to a sequential hunt group do not forward if the line is assigned to the user the call is forwarded to
IPOFFICE-32906	ARS Authorization Codes on an ETSI line causes calls to fail due to missing IE in the Setup Message
IPOFFICE-32781	1100 and 1200 Series SIP Phones - No Message Waiting Indication on a new hunt group VM Message
IPOFFICE-32720	SCN Mesh network - Speech quality on SCN calls, degrading over time.
IPOFFICE-31351	"Transfer" consultation call has the "Restricted bit" enabled (follow on from J25817)

3.2 Preferred Edition 8.0(4002) resolved field issues

The following field issues have been addressed in this release of Preferred Edition (VoiceMail Pro):

<u>JIRA Number</u>	<u>Description of Issue</u>
IPOFFICE-35270	UCM 8.0 VMPro Service is stopping
IPOFFICE-34927	Web Voicemail interface does not show time of message if left on a previous day
IPOFFICE-32357	Voicemail Pro: When playing messages some are skipped
IPOFFICE-32223	Dead Air while the VMPro services still show running - Possible Memory Leak

3.3 Customer Call Reporter 8.0.12.8 resolved field issues

The following field issues have been addressed in this release of Customer Call Reporter:

<u>JIRA Number</u>	<u>Description of Issue</u>
IPOFFICE-32121	The Talk Time values shown in the Avaya Sample ASR Standard report are 00:00:00
IPOFFICE-31756	Voicemail Report Grouped by Hour not working

3.4 one-X Portal 8.0.105(10) resolved field issues

The following field issues have been addressed in this release of one-X Portal:

<u>JIRA Number</u>	<u>Description of Issue</u>
IPOFFICE-32791	C.A. does not pop Outlook contact if contact number saved in canonical form - works OK on CA 7.0.19.6.
IPOFFICE-34264	Navigation buttons, "Page selection" field may not displayed in the 1XP Directory gadget
IPOFFICE-34125	one-X server service stops working intermittently - customer logs

3.5 User CD 4.2(48) resolved field issues

The following field issue has been addressed in this release of User CD:

3.6 Applications Server 8.0.30(2)

This release of the Applications Server consists of Preferred Edition (Voicemail Pro) 8.0(4002) and one-X Portal 8.0.106(10). Any field related fixes in these releases will also be incorporated into this edition of the Applications Server.

3.7 Unified Communications Module 8.0.10(2)

This release of the Unified Communications Module software consists of Preferred Edition (VoiceMail Pro) 8.0(4002) and one-X Portal 8.0.106(10). Any fixes in these releases will also be incorporated into this release of Unified Communications Module software.

4 Technical Notes**4.1 Upgrading IP Office core software**

When upgrading to Release 8 from a previous major release an upgrade licence is required. It is recommended that the IP Office Release 8 Software Upgrade license is installed before upgrading the system. Although the license key may not be recognized immediately by the system running an earlier major release of software, it will be recognized when the system is upgraded to Release 8.

The table below shows the necessary steps that must be taken to upgrade the IP Office system to Release 8.0:

Platform	Current Release	Upgrade Step
IP500	4.x /5.0/6.x/7.0	Load 8.0
IP500v2	6.x/7.0	Load 8.0
All modules	4.x/5.0/6.x/7.0	Load 8.0

4.2 Upgrading IP Office Administration

The IP Office Administration installer will detect previous installed versions and upgrade automatically. If a version earlier than 4.2 is installed, this must first be uninstalled before installing 8.0(51). It is not necessary to restart the PC after upgrading unless instructed to do so.

Before upgrading the IP Office system software ensure a backup of the system configuration exists.

4.3 Upgrading a remote IP500v2 System running 6.0(8) or 6.0(14) software

If the system is to be upgraded remotely and is an IP500v2 platform running 6.0(8) or 6.0(14) software please check the size of the IP Office configuration file (config.cfg) held on the system SD card **before** upgrading to this release. The config.cfg file can be found in the "Primary" folder of the System SD card. For further information please refer to "Viewing the Card Contents" in the "SD Card Management" section of the IP Office Installation Manual.

If it is determined that the IP Office configuration file stored on the System SD card has a zero byte size it is likely that the issue documented in CQ105039 has occurred. In this instance the IP500v2 system will potentially restart with a default configuration. In this instance it is recommended that the following procedure to upgrade the IP500v2 system is performed when connected to the customer's LAN:

- 1) Using Manager take a copy of the System configuration and store on the local Administration PC.
- 2) Connect to the IP Office's LAN and perform a System Restart using Manager.
- 3) When the system has restarted use Manager to send the backup of the customer's system configuration file to the IP500v2.
- 4) Restart the system and recheck the size of the IP Office configuration in the System SD card.
- 5) Upgrade the IP500v2 system to the 8.0(51) release.

4.4 IP Office Expansion Unit Compatibility

All IP Office expansion units must also be upgraded to the version supplied with the Administration software.

4.5 Upgrade Instructions for IP Office Preferred Edition

VoiceMail Pro must be at a minimum of 4.0(15) GA before automatic upgrades can be performed to Preferred Edition using this maintenance release.

The Preferred Edition 8.0(4002) installer will automatically detect the previous build and upgrade automatically. It is always advisable to back up the configuration, and any bespoke voice files prior to performing the upgrade.

Prior to upgrading the Preferred Edition Server to 8.0(4002) please ensure that all applications running on the PC are closed. The upgrade process will retain all the customer configuration, mailbox data and registry settings.

4.6 Preferred Edition Recordings – Analog trunks

On analog trunks, call disconnection can occur though busy tone detection. When such calls go to voicemail to be recorded or leave a message, when the call ends the system indicates to the voicemail server how much to remove from the end of the recording in order to remove the busy tone segment. This amount varies by system locale. For some systems it may be necessary to override the default if analog call recordings are being clipped or include busy tone. That can be done by adding the following NoUser Source Number:

VM_TRUNCATE_TIME=x

Replace “x” with the required value in the range of 0 to 7 seconds.

4.7 Upgrade Instructions for Customer Call Reporter

IP Office Customer Call Reporter 8.0 supports upgrade from only the previous two major versions - 7.0 and 6.1. To upgrade earlier versions of IP Office Customer Call Reporter, you must first upgrade your setup to one of the two previous versions. The version of SQL must also be considered before upgrading. Microsoft SQL 2005 is not supported with release 8 of the Customer Call Reporter and must be upgraded to SQL 2008. Further information can be found in the “Implementing IP Office Customer Call Reporter” manual available from the IP Office Knowledgebase.

4.8 Upgrade Instructions for IP Office Applications Server

This release of Applications Server contains no special requirements in order to upgrade from the previous GA release. For further information please refer to the Server Maintenance section of the Application Server manual available from the IP Office Knowledgebase.

5 Assistance

5.1 Documentation and Software

Documentation and Software can be downloaded from:

<http://support.avaya.com>

1. Select “Downloads & Documents”
2. Type “IP Office”
3. Select the required software release
4. Select the documentation or software categories required

Software can also be ordered on CD/DVD if required.

Issued by:
Avaya SME Customer Product Engineering Support
Contact details:-

EMEA/APAC

NA/CALA

Email: gsstier4@avaya.com

Email: IPONACALAT4@avaya.com

Internet: <http://www.avaya.com>
© 2013 Avaya Inc. All rights reserved.